

Supplementary material

Yalçın AA, Güner A, Aydın Ü, et al. Internal carotid artery stent fracture likely caused by hyoid bone compression. Kardiol Pol. 2021.

Please note that the journal is not responsible for the scientific accuracy or functionality of any supplementary material submitted by the authors. Any queries (except missing content) should be directed to the corresponding author of the article.



Figure S1. The intraoperative image shows a fractured and excised internal carotid artery stent (arrowhead)